

TS 4000  
TS 4000 S




107754-07

**GEZE**




**A**




TS 4000/4000 S  $a \leq 1400$  mm  
TS 4000 EN 5-7  $a \leq 1600$  mm

**B**






TS 4000/4000 S  $a \leq 1400$  mm  
TS 4000 EN 5-7  $a \leq 1600$  mm



**1**




**2**





[mm]





4x  
5x60  
4x  
M5x55



[mm]





4x  
5x35  
4x  
M5x20





3x  
M5x45

**3**





**4**



5



EN 2-6  
EN 5-7

EN 2-6  
EN 5-7



EN 1



EN 1



6







10 mm





i+

TS 4000



i+





TS 4000 S





7



5 mm






8



i+

TS 4000 S



9

